


PCI	CONDITION	PRIC
41.53	FAIR	
53.86	GOOD	
57.2	GOOD	
34	FAIR	
46.4	FAIR	
78.8	GOOD	
48.28	FAIR	
79.6	GOOD	
79.6	GOOD	
79.79	GOOD	
29	BAD	
34	FAIR	
78.8	GOOD	
78.8	GOOD	
77.6	GOOD	
78.4	GOOD	
43.48	FAIR	
79.2	GOOD	
72	GOOD	
64	GOOD	
49.75	FAIR	
78.8	GOOD	
31.2	FAIR	
77.6	GOOD	
31.2	FAIR	
78.4	GOOD	
29	BAD	
64	GOOD	
79.52	GOOD	
79.92	GOOD	
78.4	GOOD	
29	BAD	
78.4	GOOD	
64	GOOD	
56	GOOD	
	41.53 53.86 57.2 34 46.4 78.8 48.28 79.6 79.79 29 34 78.8 77.6 78.4 43.48 79.2 72 64 49.75 78.8 31.2 78.4 29 64 79.52 78.4 29 64 79.52 78.4 29 64 79.52 78.4 29 64 79.52 78.4 29 64 78.4 79.52 78.4 29 64 78.4 29 78.4 78.4 78.4 78.4 78.4 78.4 78.4 78.4	PCICONDITION41.53FAIR53.86GOOD57.2GOOD34FAIR78.8GOOD79.6GOOD79.6GOOD79.7GOOD79.8GOOD79.7GOOD79.8GOOD79.8GOOD79.7GOOD79.8GOOD79.8GOOD78.8GOOD78.4GOOD79.2GOOD74.4GOOD75.5FAIR78.8GOOD71.2GOOD74.4GOOD31.2FAIR78.4GOOD31.2FAIR78.4GOOD <trt< td=""></trt<>

Service Layer Credits: Esri, HERE, Garmin, OpenStreetMap contributors, and the GIS user community

TREATMENT	ACTION
Mill and Overlay	Mill and Overlay
Mill and Overlay	Mill and Overlay
Overlay	Overlay
Mill and Overlay	Mill and Overlay
Mill and Overlay	Mill and Overlay
Crack and Seal	Crack and Seal
Mill and Overlay	Mill and Overlay
Crack and Seal	Crack and Seal
Crack and Seal	Crack and Seal
Crack and Seal	Crack and Seal
Reconstruction	Reconstruction
Reconstruction	Reconstruction
Crack and Seal	Crack and Seal
Crack and Seal	Crack and Seal
Crack and Seal	Crack and Seal
Crack and Seal	Crack and Seal
Mill and Overlay	Mill and Overlay
Crack and Seal	Crack and Seal
Crack and Seal	Crack and Seal
Crack and Seal	Crack and Seal
	Reconstruction
	Crack and Seal
	Reconstruction
Crack and Seal	Crack and Seal
Reconstruction	Reconstruction
	Crack and Seal
	Reconstruction
	Crack and Seal
	Reconstruction
	Crack and Seal
	Crack and Seal
	Reconstruction
	Crack and Seal
	Crack and Seal Crack and Seal
	Reconstruction
	Overlay
Overlay	Overlay
	Mill and Overlay Mill and Overlay Overlay Mill and Overlay Mill and Overlay Crack and Seal Crack and Seal Mill and Overlay Crack and Seal Reconstruction Crack and Seal

COST	YEAR
\$447,198.43	2020
\$285,508.25	2020
\$36,315.09	2020
\$30,939.01	2020
\$341,805.86	2021
\$9,920.10	2021
\$307,141.85	2021
\$18,255.50	2021
\$18,968.55	2021
\$26,326.36	2021
<null></null>	2021
\$353,880.71	2022
\$14,196.27	2022
\$31,171.49	2022
\$20,262.60	2022
\$6,182.13	2022
\$249,714.30	2022
\$9,418.92	2022
\$17,449.17	2022
\$3,679.67	2022
\$457,569.44	2023
\$8,573.57	2023
\$133,791.10	2023
\$6,195.54	2023
\$92,034.37	2023
\$2,114.62	2024
\$79,113.02	2024
\$2,044.05	2024
\$12,723.17	2024
\$3,416.50	2024
\$9,308.73	2024
\$231,352.80	2024
\$8,103.91	2024
\$6,411.55	2024
\$135,110.84	2024
\$2,375.66	2024
\$6,840.81	2024
\$1,933.11	2024
\$8,990.69	2024
\$13,299.12	2024
\$7,325.02	2024
\$4,051.38	2024
\$4,634.14	2024
\$9,095.82	2024
\$5,499.99	2024
\$171,270.42	2024
\$2,401.23	2024





IDENTIFIER *	PCI	CONDITIO
EXCHANGE2	78.8	GOOD
EXCHANGE3	79.79	GOOD
FARM2	29	BAD
MAIN1	46.4	FAIR
MAIN2	48.28	FAIR
VILLAGE1	79.6	GOOD
VILLAGE3	79.6	GOOD



Accepted Pavement Segments

Accepted Pavement Segments

Service Layer Credits: Esri, HERE, Garmin, © OpenStreetMap contributors, and the GIS user community

ION PRIORITY

TREATMENT

- 2 Crack and Seal
- 2 Crack and Seal
- 4 Reconstruction
- 1 Mill and Overlay
- 1 Mill and Overlay
- 2 Crack and Seal
- 2 Crack and Seal

ACTION


Crack and Seal Crack and Seal Reconstruction Mill and Overlay Mill and Overlay Crack and Seal Crack and Seal

COST

\$9,920.10 \$26,326.36 <Null> \$341,805.86 \$307,141.85 \$18,255.50 \$18,968.55

Null cost indicates project costs is under water main replacement budget.





IDENTIFIER *	PCI	CONDITI
APPLEROCK	64	GOOD
AUBURN	78.4	GOOD
BALTIMORE	79.2	GOOD
BEECH	72	GOOD
EXCHANGE1	78.8	GOOD
MIDDLESEX2	78.8	GOOD
ORCHARD1	43.48	FAIR
PLEASANT3	77.6	GOOD
UNION1	34	FAIR

Legend



—— Mill and Overlay

Overlay

Crack and Seal

Accepted Pavement Segments

— Accepted Pavement Segments

Service Layer Credits: Esri, HERE, Garmin, © OpenStreetMap contributors, and the GIS user community

ION PRIORITY

TREATMENT


- 4 Crack and Seal
- 3 Crack and Seal
- 3 Crack and Seal
- 2 Mill and Overlay
- 3 Crack and Seal
- 3 Reconstruction

ACTION

Crack and Seal Mill and Overlay Crack and Seal Reconstruction COST

\$3,679.67 \$6,182.13 \$9,418.92 \$17,449.17 \$14,196.27 \$31,171.49 \$249,714.30 \$20,262.60 \$353,880.71





4 Reconstruction

3 Crack and Seal

3 Crack and Seal

2 Reconstruction

2 Mill and Overlay

IDENTIFIER *	PCI	CONDITI
BULLARD2	31.2	FAIR
DEAN	77.6	GOOD
MIDDLESEX1	78.8	GOOD
PLAIN1	31.2	FAIR
PLA IN2	49.75	FAIR

Legend

Reconstruction

Mill and Overlay

Overlay

Crack and Seal

Accepted Pavement Segments

Accepted Pavement Segments

Service Layer Credits: Esri, HERE, Garmin, © OpenStreetMap contributors, and the GIS user community

ION PRIORITY

TREATMENT


ACTION

COST


Reconstruction Crack and Seal Crack and Seal Reconstruction Reconstruction

\$92,034.37 \$6,195.54 \$8,573.57 \$133,791.10 \$457,569.44





IDENTIFIER *	PCI	CONDITION
BRANDYWINE	78.4	GOOD
BRIDGE	78.4	GOOD
BROOKVIEW	29	BAD
BULLARD1	29.41	BAD
CAUSEWAY2	70.79	GOOD
CAUSEWAY3	78.4	GOOD
CRYSTAL	64	GOOD
CURVE1	78.4	GOOD
CURVE2	78.4	GOOD
CURVE3	78.4	GOOD
DYER	79.92	GOOD
FARM1	29	BAD
GROVE	78.4	GOOD
HIMELFARB	79.52	GOOD
IRVING	78.4	GOOD
KING PHILIP	79.2	GOOD
MCCABE	64	GOOD
MONROE	64	GOOD
OAKVIEW	29	BAD
PADDOCK LN	64	GOOD
PARK2	56	GOOD
PINE HOUSE	64	GOOD



Service Layer Credits: Esri, HERE, Garmin, © OpenStreetMap contributors, and the GIS user community

DN	PRIORITY	

TREATMENT

4 Crack and Seal 4 Crack and Seal 4 Reconstruction

4 Reconstruction 4 Crack and Seal


- 4 Crack and Seal
- 4 Crack and Seal
- 4 Crack and Seal
- 4 Crack and Seal
- 4 Crack and Seal 4 Crack and Seal
- 4 Reconstruction
- 4 Crack and Seal
- 4 Reconstruction
- 4 Crack and Seal
- 4 Overlay
- 4 Crack and Seal

ACTION

Crack and Seal Crack and Seal Reconstruction Reconstruction Crack and Seal Reconstruction Crack and Seal Reconstruction Crack and Seal Overlay Crack and Seal

COST \$4,051.38 \$9,308.73 \$231,352.80 \$135,110.84 \$9,095.82 \$5,499.99 \$1,933.11 \$2,114.62 \$8,990.69 \$8,103.91 \$3,416.50 \$171,270.42 \$13,299.12 \$12,723.17 \$7,325.02 \$2,375.66 \$2,044.05 \$6,411.55 \$79,113.02 \$6,840.81 \$2,401.23 \$4,634.14





Segments in Bad Condition			
BROOKVIEW	FARM3	HOLBROOK	OLD DOVER
BULLARD1	FARM4	ISLAND2	ORCHARD2
CAUSEWAY1	FOREST1	LAVENDER1	POLLARD1
FARM1	FOREST2	LEXINGTON	SARATOGA
FARM2	FRONTIER	OAKVIEW	WALNUT
Segments in Fair Condition			
ALMA	HERITAGE PATH	ORCHARD1	SOUTH END POND
BOGASTOW	HIGH	PARK1	SOUTHWOODS CIR
BOW	INDEPENDENCE	PARTRIDGE LN	SPRING2
BUDDY KEARNY	IRONWOOD	PINE VALLEY RD	TARA
BULLARD2	ISLAND3	PINE VIEW	TICONDEROGA
CASTLE	J WM HEIGHTS	PLAIN1	TIMBERLINE
CEDAR	KENNEDY TER	PLAIN2	TOWN
CLARK	KLIFFORD	PLEASANT1	TRACY
CLEWES	LARCH	POLLARD2	TURNER
COLE	LAVENDER2	PONDVIEW	UNION1
CONCORD	MAIN1	RAILROAD	UNION2
COTTAGE	MAIN2	RIDGE1	UNNAMED21
CRESTVIEW	MAPLE	RIDGE2	VAN KLEEK
DALE	MILLISTON	ROSE RD	VILLAGE2
DANIELS	MORSE	ROSENFELD	WAINWRIGHT CIR
ENVIRONMENTAL	MYRTLE	RYAN	WALNUT HILL
EVERGREEN	NORFOLK	SHANNON LN	WINTER
HAMMOND LN	NORTH	SHERMAN	WOODLAWN
Segments in Good Condition			
ACORN	CURVE1	HIMELFARB	PINE HOUSE
ADAMS	CURVE2	IRVING	PLEASANT2
APPLEROCK	CURVE3	KING PHILIP	PLEASANT3
AUBURN	DEAN	MAIN3	RIDGE3
BALTIMORE	DOVER1	MCCABE	ROLLING MEADOW
BEECH	DYER	MIDDLESEX1	SANDSTONE
BIRCH	EXCHANGE1	MIDDLESEX2	SPENCER
BLUEBERRY	EXCHANGE2	MONROE	UNION3
BRANDYWINE	EXCHANGE3	ORCHARD3	VILLAGE1
BRIDGE	GERALD	PADDOCK LN	VILLAGE3
CAUSEWAY2	GRANITE	PARK2	WATER
CAUSEWAY3	GROVE	PARNELL	WINDCREST LN
CRYSTAL	HILLTOP		
			\frown
			KLEI
			Brig

Service Layer Credits: Esri, HERE, Garmin, © OpenStreetMap contributors, and the GIS user community

Millis, MA Road Condition Assessment

